



Product Technical Info

TIMING BEL KIT - TBK5073.11

AVVERTENZE SUL CORRETTO MONTAGGIO	WARNING INSTRUCTIONS FOR A CORRECT ASSEMBLY
<p>L'immagine sottostante è una puleggia smorzatrice per la quale RENAULT raccomanda la sostituzione ogni volta che si sostituisce il kit distribuzione. La sostituzione è raccomandata in quanto tale puleggia contribuisce attivamente allo smorzamento delle vibrazioni assieme al tendicinghia automatico.</p> <p>Poiché l'azione di smorzamento logora in ugual misura il tenditore e tutti gli altri componenti, al fine di evitare spiacevoli inconvenienti, si consiglia di sostituire anche la puleggia nell'immagine sotto riportata.</p>	<p>The illustration below shows a damping pulley whose replacement is recommended by RENAULT every time the timing kit is replaced. The replacement is recommended because this pulley actively aids the damping of all vibrations in cooperation with the automatic belt tensioner.</p> <p>As the damping action wears the tensioner and all other components in the same way, it is recommended to replace the pulley in the illustration below at the same time.</p>



<p>I suggerimenti e/o lo schema di montaggio eventualmente presente sono solo a titolo indicativo. La EXO Automotive Spa non si assume alcuna responsabilità derivante da eventuali errori e/o omissioni e/o modifiche successive apportate al sistema da parte del Costruttore del veicolo. Si consiglia altresì di avvalersi dei dati aggiornati forniti da quest'ultimo.</p>	<p>Recommendations and/or assembly diagram shown here are only for explanation purposes. EXO Automotive Spa doesn't accept any responsibility due to any later error and/or omission and/or modification made by the vehicle manufacturer to the system itself. It is further recommended to use state-of-the-art data supplied by the manufacturer.</p>
---	--